

Document Name	HSE-FOR-8.1.1 Water Pump Prestart Check
Document ID	CA-ZAM-KAL-IR-001
Version Date	10/13/2025
Version	1.0
Approved	sfds
Country	Zambia
Project	Kalumbila

HSE-FOR-8.1.1 Water Pump Prestart Check
NO: ZAM-KAL-IR-001

DATE	10/13/2025
SITE / PROJECT	Kalumbila
INSPECTOR	sfds

COMPRESSOR No	Light vehicle-01
HOURS	6565659196 Hours

1. ALL DEFECTS UNDER "A" CLASSIFICATION TO BE ATTENDED IMMEDIATELY
2. ALL DEFECTS UNDER "B" CLASSIFICATION TO BE ATTENDED WITHIN 48 HOURS
3. ALL DEFECTS UNDER "C" CLASSIFICATION TO BE ATTENDED TO AS SOON AS POSSIBLE

DESCRIPTION	CLASS	OKAY	FAULTY	N/A	COMMENT
DRIP TRAY / BUNDING	B		X		
5 METER AWAY FROM WATER SOURCE	B		X		
FIRE EXTINGUISHER & SIGNAGE	B			—	
ENGINE OIL LEVEL	B		X		
RADIATOR COOLANT (IF APPLICABLE)	B			—	
REMARKS	54				

Overall Condition	Minor Repair required	
Vehicle Safe To Use	No	Signature: Not Provided
Maintenance Priority	Medium	

CORRECTIVE ACTION ITEMS

Equipment Condition After Correction: Unsatisfactory

Role: Operator

Mechanic Name: N/A

Operator Name: ghj

S.No	Item	Status
1	DRIP TRAY / BUNDING	Not Fixed
2	5 METER AWAY FROM WATER SOURCE	No need
3	ENGINE OIL LEVEL	Not Fixed

Mechanic Signature

Not Provided

Operator Signature

